

CREW: 157

WORK ORDER TYPE: PD REPAIR

03-96033-44

ISSUE DATE 01/06/11

Page 1 Of 3

Originator : WILLIAM LOVELL

Schedule Date :

Date Completed: _____

Failure Code: _____

Planner : RONALD TAYLOR

Priority : 3A

Drawing No : 2CAB-M2016A

Clearance : NO

Completed By : _____

Signature : _____

Equip No/Cat: 2CAB--0 7

Tag Request :

Project ID :

Text ID :

Accepted By : _____

Signature : _____

Shutdown : U Unit

Frequency : NOT SCHEDULED

Ref No :

Last Reading : No Reading

**** Delay Codes Legend ******W=Whse C=CrSp T=Tag TL=Tool P=Plan**
**** Record Time Daily ****
Delays

Step	Job Scope	MN	DY	Safety and Additional Information	Emp No	Date	Hours	Code/Hrs
1	REPLACE THE DAMAGED CONTROL AIR TUBING IN UNIT-2 GOING TO INSTRUMENT ENCLOSURE, 2COE-IRK-25. ** THIS AIR LINE WAS TORN AWAY FROM IT'S ANCHOR POINTS AND BENT UP IN AN ARCH DURING THE REMOVAL/REPLACEMENT OF THE NEW ABT BURNERS. ** REMOVE AND REPLACE DAMAGED AIR LINE, REPAIR/REPLACE HANGERS AS NEEDED. LOCATION: U-2, 6TH FLOOR, NORTH SIDE OF BOILER, EAST STAIRWAY, BURNER ACCESS ***** JOB SCOPE: ***** A. VERIFY AND SIGN ONTO CLEARANCE. B. REMOVE AND REPLACE ANY DAMAGED TUBING, ELBOWS, ETC. FROM THE MAIN CONTROL AIR LINE TO THE INSTRUMENT ENCLOSURE AS NEEDED. C. INSTALL NEW ELBOWS AND TUBING, AS NECESSARY. D. REPAIR OR REPLACE DAMAGED OR MISSING HANGERS/SUPPORTS FOR THE AIR LINE AND ATTACH AS NEEDED. E. CLEAN UP AFTER YOURSELF PLEASE.	2	1	0990.07102V, 0990.04107V(2X), HW, WC, SPC, XT(4X), 0690.06142V, 0690.05332, 0690.05128V, 0607.016(3X). (2X) ** SAFETY / ENVIRONMENTAL REQUIREMENTS: ** 1. HOT WORK PERMIT REQUIRED. 2. TIE-OFF WHILE WORKING FROM LADDER OR SCAFFOLD. 3. WEAR ALL REQUIRED PPE AND RECOMMENDED WELDING PPE. ***** ADDITIONAL INFORMATION ***** 1. SOME PARTS HAVE BEEN STAGED FOR THIS WORK ORDER. 2. TUBING AND FITTINGS = COPPER. 3. STOCK NUMBERS THAT MIGHT BE HANDY: TUBING === (DIRECT) 3/4"ID, TYPE K ELBOW ==== 34954 (90 deg.) COUPLING = 03267				

**** IMPORTANT NOTICE ****
YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



03-96033-44

IP7_032356

CREW: 157

WORK ORDER TYPE: PD REPAIR

03-96033-44

ISSUE DATE 01/06/11

Page 2 Of 3

Step Job Scope Cont'd

MN DY

Safety and Additional Information Cont'd

Notes Cont'd:

1

** ADDITIONAL INSTRUCTION BY SUPERVISOR **

IP7_032357

CREW: 157

WORK ORDER TYPE: PD REPAIR

03-96033-44

ISSUE DATE 01/06/11

Page 3 Of 3

** Work Order Parts List **

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1 03267	FITTING, COPPER SOLDER	S 282119*	04/21/04	EA	3	0	3
2 34954	FITTING, COPPER SOLDER	S 282119*	04/21/04	EA	3	0	3
3 52441	BRUSH, ACID	S 308013	02/12/05	EA	2	0	2
4 DIRECT	TUBING, COPPER, 3/4" ID, TYPE K, 7/8" OD, WALL .065", 20 FT	04-39384	05/25/04	FT	60	0	60

IP7_032358